



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)

Invoice Number  
**596261**

### EQUIPMENT INSPECTED

State Number: 8633      Type of Unit: Freight      Landings: 3      Manuf: SOUTHERN  
Capacity: 10000      Installed: 07/08/1976      Complied: 07/08/1976      Speed: 60  
Volts: 560      Floor to Floor: 1 to 3      Entrances: 2      Rope Size:  
Owner: AVOCA INC, PO BOX 129, MERRY HILL, NC, 27957  
Occupant: AVOCA INC, 841 AVOCA FARM ROAD, MERRY HILL, NC, 27957

### INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
08/20/2008	Routine	Re-issued	49 - Hayes	BERTIE	8

Violation Abatement Date: 08/20/2008

### VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

n/a      No violations found

Violations pointed out to: Maintenance

Inspector \_\_\_\_\_

### INVOICE

No other invoice will be issued.  
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,  
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: AVOCA INC, PO BOX 129, MERRY HILL, NC, 27957  
Occupant: AVOCA INC, 841 AVOCA FARM ROAD, MERRY HILL, NC, 27957

Invoice Number  
**596261**  
State Nbr: 8633  
Date: 08/20/2008  
Fee: \$175