

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm

Invoice Number
636021

		EQUIPME	NT INSPECTE	D		
State Number: 19198 Type of Unit: Passer Capacity: 2500 Installed: 12/08/2000		-			Manuf: THYSSEN KRUPP Speed: 95 Rope Size: 0	
Floor to Floor: 1 to 2 Entrar						
	Y SCHOOLS, P.O. BOX 1				G 20646	
•	NORE ELEMENTARY, 10					
			N INFORMAT			
Inspection Date 02/24/2009	Type Inspection Routine	Certificate Status Re-issued		Inspector - Henegar	County Name AVERY	County Code 6
Violation Abatement I	Date: 03/26/2009	VIOLATION	S FOUND			
quipment into compliance				ng corrections	have been made in orde	er to bring your
	Take steps to install oil drain line tub in pit can. Take steps to perform the annual relief valve test					

INVOICE

No other invoice will be issued.

If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division, 1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: AVERY COUNTY SCHOOLS, P.O. BOX 1360, NEWLAND, NC, 28657

Occupant: NEW CROSSNORE ELEMENTARY, 1000 WALT CLARK ROAD, CROSSNORE,

NC, 28616

Invoice Number 636021

State Nbr: 19198 02/24/2009 Date: Fee:

\$175