



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
636033

EQUIPMENT INSPECTED

State Number: H1558	Type of Unit: Hand Lift	Landings: 3	Manuf: NATL W-O-V
Capacity: 750	Installed: 12/14/2004	Complied: 01/04/2005	Speed: 20
Volts: 115	Floor to Floor: 1 to 3	Entrances: 3	Rope Size: 0
Owner: FIRST BAPTIST CHURCH, 220 EAST CROSSNORE DRIVE, CROSSNORE, NC, 28616			
Occupant: FIRST BAPTIST CHURCH, 220 EAST CROSSNORE DRIVE, CROSSNORE, NC, 28616			

INSPECTION INFORMATION

Inspection Date 02/26/2009	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 4 - Henegar	County Name AVERY	County Code 6
-------------------------------	----------------------------------	----------------------------------	--------------------------	----------------------	------------------

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

BLDG. CLOSED

Violations pointed out to: N/A

Inspector _____

INVOICE

No other invoice will be issued.

If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: FIRST BAPTIST CHURCH, 220 EAST CROSSNORE DRIVE, CROSSNORE, NC,
28616
Occupant: FIRST BAPTIST CHURCH, 220 EAST CROSSNORE DRIVE, CROSSNORE, NC,
28616

Invoice Number
636033

State Nbr: H1558
Date: 02/26/2009
Fee: \$0