

NC, 28681

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm Invoice Number 636117

\$0

Fee:

		EQUIPMENT IN	SPECTED			
State Number: H1357 Type of Unit: Hand Lift Capacity: 750 Installed: 03/20/2003 Volts: 120 Floor to Floor: 1 to 2 Dwner: MT. NEBO BAPTIST CHURCH, 2600 OLD MOUNTAIL Decupant: MT. NEBO BAPTIST CHURCH, 2600 OLD MOUNTAIL		20/2003 : 1 to 2 :LD MOUNTAIN ROAD		Speed: 20 Rope Size: 0 C, 28681	Rope Size: 0	
		INSPECTION INFO	DRMATION			
Inspection Date 03/25/2009	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 4 - Henegar	County Name (ALEXANDER	County Code 2	
		VIOLATIONS F	FOUND			
Notify the Elevator Bu		eted Violations Form when uipment into compliance		ons have been made in order	to bring you	
Violations pointed out to: N/A			Inspector			
		INVOIC	E			
If not paid withi Return this stub with pays 1101 Mail Service Center Owner: MT. NEBO BAI NC, 28681	ment to: NC Department of Raleigh, NC 27699-110	voice, your certificate bed of Labor, Budget and Purd 1	chasing Division,	Invoice Nu 636117 State Nbr: H13: Date: 03/25 Fee: \$0		

Occupant: MT. NEBO BAPTIST CHURCH, 2600 OLD MOUNTAIN ROAD, TAYLORSVILLE,