



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**10004-36-2262**  
State Number  
**17838**

EQUIPMENT INSPECTED

State Number: <b>17838</b>	Type of Unit: Passenger	Floor to Floor: LL to 2
Capacity: 3500	Manuf: SCHINDLER	Speed: 100
Landings: 3	Installed: 01/04/1999	Rope Size:
Volts: 200	Complied: 01/05/1999	Entrances: 1
OWNER	OCCUPANT	
HOMEPLACE OF BURLINGTON	HOMEPLACE OF BURLINGTON	
118 ALAMANCE RD	118 ALAMANCE RD	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 01/04/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

No violations found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: office

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

HOMEPLACE OF BURLINGTON  
118 ALAMANCE RD  
BURLINGTON, NC, 27215