

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10005-36-0663 State Number 3042

1

	E	EQUIPMENT INSPECTED			
State Number: 3042	Type of Unit: Passenger Manuf: THYSSEN KRUPP Installed: 01/14/1957		Floor to Floor:	Floor to Floor: 1 to 3 Speed: 100 Rope Size:	
Capacity: 6000			Speed: 100		
Landings: 3			Rope Size:		
Volts: 440	Complied: 01/14/1957		Entrances: 1		
OWNER	OCCUPANT				
AMI	AMI				
2609 TUCKER ST	204 GRA-HOPEDALE RD				
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
	INS	SPECTION INFORMATION			
Inspection Date 01/05/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
No violations found					
Notify the Elevator Bureau in wromplainace with current codes.	iting on Corrected Violations Form v	when the following corrections	have been made in order to bri	ng your equipment into	
violations pointed out to: Jay					
	To make changes to the invoice ma				
THIS IS NOT AN	-	AMI			
INVOICE	An invoice will be mailed to:	2609 TUCKER ST BURLINGTON NC. 27	215		