NCD DL NC Oppartment of Labor

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10012-12-3273 State Number 4767

	EÇ	QUIPMENT INSPECTED		
State Number: 4767	Type of Unit: Freight		Floor to Floor: 1 to 3	
Capacity: 5000	Manuf: WESTBR	-	Speed: 75	
Landings: 3	Installed: 07/09/19	Installed: 07/09/1962		
Volts: 220	Complied: 08/29/1	1962	Rope Size: Entrances: 2	
OWNER		OCCUPANT		
ACME MCCRARY CORP	CME MCCRARY CORP ACME MCCRARY CORP			
BOX 1287 159 NORTH ST ASHEBORO, NC, 27204-1287 ASHEBORO, NC, 27203				
		PECTION INFORMATION		
Inspection Date 01/12/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 12 - Essick	County RANDOLPH 7
		VIOLATIONS		
complainace with current codes. Violations pointed out to: Maintenance		Elevator Name: Shipping and Receiving on the following corrections have been made in order to bring your equipment into		
	To make changes to the invoice mail			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	ACME MCCRARY CORF BOX 1287 ASHEBORO, NC, 27204-)	