N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
10028-16-1835
State Number
6917

EQUIPMENT INSPECTED

State Number: **6917**	Type of Unit: Dumbwaiter	Floor to Floor: 1 to 2
Capacity: 300	Manuf: MATOT	Speed: 50
Landings: 2	Installed: 01/28/1971	Rope Size: 1/4
Volts: 270	Complied: 01/28/1971	Entrances: 1

OWNER	OCCUPANT
BEAUFORT COUNTY	BEAUFORT CO COMMUNITY COLLEGE
PO BOX 1069	5337 HWY 264 EAST
WASHINGTON, NC, 27889	WASHINGTON, NC, 27889

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County
01/28/2010	Routine	Re-issued	16 - Moore	BEAUFORT

7

VIOLATIONS

n/a	No violations found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: Melvin Lodge Inspector _____

THIS IS NOT AN INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:
BEAUFORT COUNTY
PO BOX 1069
WASHINGTON, NC, 27889