



INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**10035-12-4761**  
State Number  
**16142**

EQUIPMENT INSPECTED

State Number: <b>16142</b>	Type of Unit: Passenger	Floor to Floor: 1 to 4
Capacity: 8000	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 4	Installed: 03/28/1996	Rope Size: 5/8
Volts: 480	Complied: 04/10/1996	Entrances: 1

OWNER	OCCUPANT
STAR PET	STAR PET
801 PINEVIEW RD	801 PINEVIEW RD
ASHEBORO, NC, 27203	ASHEBORO, NC, 27203

INSPECTION INFORMATION

Inspection Date 02/04/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 12 - Essick	County RANDOLPH
-------------------------------	----------------------------	---------------------------------	--------------------------	--------------------

76

VIOLATIONS

2.2 Make all pit lights function. One light fixture is loose

Items must be corrected by: 03/06/2010

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: John, Maintenance

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

STAR PET  
801 PINEVIEW RD  
ASHEBORO, NC, 27203