



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
10035-36-5816
State Number
2850

EQUIPMENT INSPECTED

State Number: 2850	Type of Unit: Freight	Floor to Floor: B to 2
Capacity: 4000	Manuf: MONARCH	Speed: 75
Landings: 3	Installed: 09/13/1956	Rope Size:
Volts: 208	Complied: 09/13/1956	Entrances: 1
OWNER	OCCUPANT	
JOHN BURTON-CHADPRTAFIELD	MAI STREET FLEA MARKET	
PO BOX 2038	612 S MAIN ST	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 02/04/2010	Type Inspection Routine	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	----------------------------------	---------------------------	--------------------

VIOLATIONS

2.7.3.4.1(b)	Provide a self closing, self locking machine room door.
8.11.2.2.2	Perform the annual no load safety test
8.6	TAKE STEPS TO PROPERLY SERVICE ELEVATOR
8.6	REPLACE MISSING LIGHT GUARD IN CAR

Items must be corrected by: 03/06/2010

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: JOHN BURTON

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

JOHN BURTON-CHADPRTAFIELD
PO BOX 2038
BURLINGTON, NC, 27215