

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10043-36-207 State Number 4872

1

	E	EQUIPMENT INSPECTED			
State Number: 4872	Type of Unit: Freig	Floor to Floor:	Floor to Floor: 1 to 2 Speed: 40 Rope Size:		
Capacity: 1500	Manuf: THYSSEN KRUPP Installed: 05/10/1963				Speed: 40
Landings: 2					Rope Size:
Volts: 480	Complied: 06/19/1963		Entrances: 1		
OWNER		OCCUPANT			
CAROLINA ACTIVITIES INC		WHITE EST			
202 N FIFTH ST	202 N FIFTH ST				
MEBANE, NC, 27203		MEBANE, NC, 27203			
	INS	SPECTION INFORMATION			
Inspection Date 02/12/2010	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
LEFT ELEVATOR NOTIFICA	TION				
Notify the Elevator Bureau in writing omplainace with current codes.	ng on Corrected Violations Form v	when the following corrections l	nave been made in order to bri	ing your equipment into	
violations pointed out to: OFFICE					
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN	6	= =	CAROLINA ACTIVITIES INC		
	An invoice will be mailed to:	202 N FIFTH ST	-		

MEBANE, NC, 27203