

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10048-36-4512 State Number 6260

1

	E	QUIPMENT INSPECTED			
State Number: 6260	Type of Unit: Passenger		Floor to Floor: 1 t	Floor to Floor: 1 to 2	
Capacity: 2000	Manuf: SOUTHERN		Speed: 75	Speed: 75	
Landings: 2	Installed: 01/13/1969		Rope Size:		
Volts: 220	Complied: 05/07/	1996	Entrances: 1		
OWNER	OCCUPANT				
CAROLINA BIO SUPPLY	CAROLINA BIO SUPPLY				
2700 YORK RD		2700 YORK RD			
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
	INS	SPECTION INFORMATION			
Inspection Date 02/17/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
No violations found					
	iting on Corrected Violations Form v	when the following corrections h	nave been made in order to bri	ng your equipment into	
omplainace with current codes.			•		
violations pointed out to: office					
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	CAROLINA BIO SUPPL 2700 YORK RD BURLINGTON NC 272			