



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
10064-36-0046
State Number
23251

EQUIPMENT INSPECTED

State Number: 23251	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 06/20/2005	Rope Size:
Volts: 480	Complied: 06/20/2005	Entrances: 1
OWNER	OCCUPANT	
KIDDE	KIDDE	
1061 CORPORATE DR	1061 CORPORATE DR	
MEBANE, NC, 27617	MEBANE, NC, 27617	

INSPECTION INFORMATION

Inspection Date 03/05/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

No violations found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: office

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

KIDDE
1061 CORPORATE DR
MEBANE, NC, 27617