



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**10069-4-4365**  
State Number  
**H1097**

EQUIPMENT INSPECTED

State Number: <b>H1097</b>	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: ACCESS	Speed: 15
Landings: 2	Installed: 03/29/2001	Rope Size: 0
Volts: 120	Complied: 04/04/2001	Entrances: 2
OWNER	OCCUPANT	
NEWLAND FIRST BAPTIST CHURCH	NEWLAND FIRST BAPTIST CHURCH	
160 CRANBERRY STREET	160 CRANBERRY STREET	
NEWLAND, NC, 28657	NEWLAND, NC, 28657	

INSPECTION INFORMATION

Inspection Date 03/10/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 4 - Henegar	County AVERY
-------------------------------	----------------------------	---------------------------------	--------------------------	-----------------

6

VIOLATIONS

n/a No violations found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Newland First Baptist # 828-73309092

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

NEWLAND FIRST BAPTIST CHURCH  
160 CRANBERRY STREET  
NEWLAND, NC, 28657