



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
10070-4-105
State Number
H1558

EQUIPMENT INSPECTED

State Number: H1558	Type of Unit: Hand Lift	Floor to Floor: 1 to 3
Capacity: 750	Manuf: NATL W-O-V	Speed: 20
Landings: 3	Installed: 12/14/2004	Rope Size: 0
Volts: 115	Complied: 01/04/2005	Entrances: 3

OWNER

FIRST BAPTIST CHURCH
220 EAST CROSSNORE DRIVE
CROSSNORE, NC, 28616

OCCUPANT

FIRST BAPTIST CHURCH
220 EAST CROSSNORE DRIVE
CROSSNORE, NC, 28616

INSPECTION INFORMATION

Inspection Date 03/11/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 4 - Henegar	County AVERY
-------------------------------	----------------------------	---------------------------------	--------------------------	-----------------

6

VIOLATIONS

n/a No violations found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: First Baptist # 828-733-5243

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

FIRST BAPTIST CHURCH
220 EAST CROSSNORE DRIVE
CROSSNORE, NC, 28616