

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10081-4-1654 State Number 488

	EQI	UIPMENT INSPECTED			
State Number: 488	Type of Unit: Freigh	t	Floor to Floor: 1 to	3	
Capacity: 2000	Manuf: MONARCH Installed: 09/05/1945		Speed: 75		
Landings: 3			Rope Size: 1/2		
Volts: 220	Complied: 09/05/194	15	Entrances: 1		
OWNER	OCCUPANT				
LINDLE & ASSOCIATES	LINDLE & ASSOCIATES				
23 EAST MAIN AVENUE	23 EAST MAIN AVENUE				
TAYLORSVILLE, NC, 28681		TAYLORSVILLE, NC, 28681			
	INSPI	ECTION INFORMATION			
Inspection Date 03/22/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 4 - Henegar	County ALEXANDER	
		VIOLATIONS			
complainace with current codes. Violations pointed out to: Lindle	ting on Corrected Violations Form who & Associates # 828-635-0535		Inspector		
	To make changes to the invoice mailing				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	LINDLE & ASSOCIATES 23 EAST MAIN AVENUE TAYLORSVILLE, NC, 286			