

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10083-4-1148 State Number 13317

	EQ	UIPMENT INSPECTED			
State Number: 13317 Capacity: 2100 Landings: 2	Type of Unit: Pas: Manuf: SOUTHE Installed: 08/23/19	RN 989	Floor to Floor: 1 to 2 Speed: 100 Rope Size: 0		
Volts: 208	Complied: 08/23/	1989	Entrances: 1		
OWNER		OCCUPANT			
GRANDFATHER COUNTRY CLUB 2120 HWY.105 NORTH		GRANDFATHER COL	GRANDFATHER COUNTRY CLUB 1225 HWY.105 NORTH		
		1225 HWY.105 NORT			
LINVILLE, NC, 28646 LINVILLE, NC, 28646					
	INSP	ECTION INFORMATION			
Inspection Date 03/24/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 4 - Henegar	County AVERY 6	
		VIOLATIONS			
	riting on Corrected Violations Form wh	en the following corrections have l	peen made in order to bring you	r equipment into	
complainace with current codes	•	-			
	dfather Country Club # 828-89604531		Inspector		
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	GRANDFATHER COUNTRY 2120 HWY.105 NORTH LINVILLE. NC. 28646	CLUB CLUB		