

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10091-36-0278 State Number 5904

1

	E	QUIPMENT INSPECTED		
State Number: 5904	Type of Unit: Fre		Floor to Floor: 1 to	o 2
Capacity: 3000	Manuf: WESTBROOK		Speed: 35	
Landings: 2	Installed: 08/09/1967		Rope Size:	
Volts: 550	Complied: 09/19/	/1994	Entrances: 1	
OWNER	OCCUPANT			
KINGSDOWN INC	KINGSDOWN INC			
126 W HOLT ST		126 W HOLT ST		
MEBANE, NC, 27302		MEBANE, NC, 2'	7302	
	INS	PECTION INFORMATION		
Inspection Date 04/01/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
		VIOLATIONS		
No violations found				
otify the Elevator Bureau in wi	riting on Corrected Violations Form w	when the following corrections h	nave been made in order to bri	ing your equipment into
iolations pointed out to: office	;			
	To make changes to the invoice ma			
THIS IS NOT AN INVOICE		KINGSDOWN INC		
	An invoice will be mailed to:	126 W HOLT ST MEBANE, NC, 27302		