

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
www.nclabor.com/elevator.htm  
919-807-2770

Report Number <b>10091-36-4492</b> State Number <b>2153</b>
--

EQUIPMENT INSPECTED

State Number: <b>2153</b>	Type of Unit: Freight	Floor to Floor: 1 to 3
Capacity: 4000	Manuf: MONARCH	Speed: 60
Landings: 3	Installed: 07/22/1953	Rope Size:
Volts: 550	Complied: 07/22/1953	Entrances: 2
OWNER INTERNATIONAL TEXTILE GROUP, INC. 906 ANTHONY ST BURLINGTON, NC, 27215		OCCUPANT BURLINGTON FINISHING 906 ANTHONY ST BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 04/01/2010	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------------	----------------------------------	---------------------------	--------------------

1

VIOLATIONS

unable to gain access will try later

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: n/a/

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

INTERNATIONAL TEXTILE GROUP, INC.  
906 ANTHONY ST  
BURLINGTON, NC, 27215