



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**10102-48-2278**  
State Number  
**24471**

EQUIPMENT INSPECTED

State Number: <b>24471</b>	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: SCHINDLER, HYD	Speed: 100
Landings: 2	Installed: 12/14/2006	Rope Size: 0
Volts: 208	Complied:	Entrances: 1
OWNER	OCCUPANT	
SECURITY SAVINGS BANK	SECURITY SAVINGS BANK	
5201 SOUTHPORT SUPPLY RD	5201 SOUTHPORT SUPPLY RD	
SOUTHPORT, NC, 28465	SOUTHPORT, NC, 28465	

INSPECTION INFORMATION

Inspection Date 04/12/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

n/a	No violations found
n/a	No violations found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: PAT GARRELL

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

SECURITY SAVINGS BANK  
5201 SOUTHPORT SUPPLY RD  
SOUTHPORT, NC, 28465