

Violations pointed out to: MANDY

THIS IS NOT AN

INVOICE

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10103-48-1970 State Number 21788

EQUIPMENT INSPECTED						
State Number: 21788 Type of		Type of Unit:	Passenger	Floor to Floor: 1 to 2		_
Capacity: 2500 Manuf: G			S	Speed: 100	Speed: 100	
Landings: 2 Installed		Installed: 06	/25/2003	Rope Size: 0	Rope Size: 0	
Volts: 208 Complie		Complied: 0	6/25/2003	Entrances: 1	Entrances: 1	
OWNER			OCCUPANT			
SHALLOTTE PRESBYTERIAN CHURCH			SHALLOTTE PRSBYTERIAN CHURCH			
POB 251; 5070 ROURK DR			5070 ROURK DRIVE			
SHALLOTTE, NC, 28459			SHALLOTTE, NC, 28459			
			NSPECTION INFORMATION			
Inspection Date 04/13/2010		Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	10
			VIOLATIONS			
2.7.2.1	Elevator ed	Elevator equipment only to be located in the machine room.				
8.6.4.7.4	Remove th	Remove the water from the pit floor.				
Items must	be corrected by: (	05/03/2010				
Notify the Eleva complainace wit		iting on Corrected Violations Form	m when the following corrections	have been made in order to	bring your equipment into	

SHALLOTTE PRESBYTERIAN CHURCH

POB 251; 5070 ROURK DR SHALLOTTE, NC, 28459

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

Inspector \_\_