

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-807-2770

Report Number
10104-36-0829
State Number
15908

EQUIPMENT INSPECTED

State Number: **15908** Type of Unit: Passenger Floor to Floor: 1 to 2
Capacity: 2500 Manuf: THYSSEN KRUPP Speed: 100
Landings: 2 Installed: 06/26/1995 Rope Size:
Volts: 460 Complied: 06/28/1995 Entrances: 1

OWNER
ANDY ALBRIGHT
215 ALTAMAHAWA UNION RIDGE ROAD
BURLINGTON, NC, 27215

OCCUPANT
NATIONAL AGENTS ALLIANCE
1214 TURRENTINE ST
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County
04/14/2010	Routine	Re-issued	36 - Kirkman	ALAMANCE

1

VIOLATIONS

No violations found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: office

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ANDY ALBRIGHT
215 ALTAMAHAWA UNION RIDGE ROAD
BURLINGTON, NC, 27215