



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
10120-36-3698
State Number
25793

EQUIPMENT INSPECTED

State Number: 25793	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 06/27/2008	Rope Size:
Volts: 480	Complied: 06/27/2008	Entrances: 1
OWNER	OCCUPANT	
CAROUSEL CINEMAS @ ALAMANCE CROSSING	CAROUSEL CINEMAS @ ALAMANCE CROSSING	
1090 PIPER LANE	1090 PIPER LANE	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 04/30/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

8.6.4.8.1	Clean the elevator machine room.
8.6	REPAIR IN CAR PUSH BUTOONS. THE OUTSIDE OF THE BUTTONS ARE DETERIATING
8.6.4.7.1	Clean the elevator pit.
8.6.5.7	Provide an oil usage log.
8.6.10.1	Provide a monthly log of the results of the Phase I and Phase II activations.

Items must be corrected by: 05/30/2010

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: OFFICE

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CAROUSEL CINEMAS @ ALAMANCE CROSSING
1090 PIPER LANE
BURLINGTON, NC, 27215