

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10123-36-1233 State Number 15764

1

	E	QUIPMENT INSPECTED			
State Number: 15764	Type of Unit: Pass	Type of Unit: Passenger		Floor to Floor: 1 to 2	
Capacity: 2100	Manuf: THYSSEN	Manuf: THYSSEN KRUPP		Speed: 125	
Landings: 3	Installed: 05/04/19	Installed: 05/04/1995		Rope Size:	
Volts: 208	Complied: 05/04/1	1995	Entrances: 1		
OWNER		OCCUPANT			
FIRST BAPTIST CHURCH		FIRST BAPTIST CHURCH			
301 S THIRD STREET		301 S THIRD STREET			
MEBANE, NC, 27302		MEBANE, NC, 27302			
	INS	SPECTION INFORMATION			
Inspection Date 05/03/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
No violations found					
Notify the Elevator Bureau in wromplainace with current codes.	riting on Corrected Violations Form v	when the following corrections l	have been made in order to bri	ing your equipment into	
Violations pointed out to: office	,				
	To make changes to the invoice ma				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	FIRST BAPTIST CHUR 301 S THIRD STREET MEBANE, NC, 27302	СН		