

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10144-48-4650 State Number 12790

|  |   | EQUIPMENT INSPECTED             |                               |                     |  |
|--|---|---------------------------------|-------------------------------|---------------------|--|
| State Number: 12790 Type of Unit: Passer |   | Passenger                       | enger Floor to Floor: G to 15 |                     |  |
| Capacity: 2500                           | Manuf: OTIS   | Manuf: OTIS                     |                               | Speed: 200          |  |
| Landings: 16 Installed: 05/09/1988       |   | 09/1988                         | Rope Size: 5/8                |                     |  |
| Volts: 480 Complied: 06/10/1988          |   | /10/1988                        | 988 Entrances: 1              |                     |  |
| OWNER                                    |   |                                 | OCCUPANT                      |                     |  |
| BENCHMARK MGMT                           | ENCHMARK MGMT (OCEANPOINT) OCEAN POINT CONDO                |                                 |                               |                     |  |
| ATTN JAME WHIELDON                       |   |                                 | ONE W OCEAN BLVD              |                     |  |
| N MYRTLE BEACH, SO                       | MYRTLE BEACH, SC, 29597 OCEAN ISLE, NC, 28459               |                                 | 9                             |                     |  |
|  |   | INSPECTION INFORMATION          |                               |                     |  |
| Inspection Date<br>05/24/2010            | Type Inspection<br>Routine                                  | Certificate Status<br>Re-issued | Inspector<br>48 - Martin      | County<br>BRUNSWICK |  |
|  |   | VIOLATIONS                      |                               |                     |  |
| 8.6.4.9 CI                               | ean the car top of all debris.                              |                                 |                               |                     |  |
| 2.27.1.1.2 Pu                            | Put the in car emergency telephone in proper working order. |                                 |                               |                     |  |

Items must be corrected by: 06/13/2010

Clean the elevator pit.

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: BOB SCHERER Inspector \_\_\_\_\_

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

8.6.4.7.1

BENCHMARK MGMT (OCEANPOINT)
An invoice will be mailed to: ATTN JAME WHIELDON

ATTN JAME WHIELDON N MYRTLE BEACH, SC, 29597