

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10145-48-0054 State Number 24949

		EQUIPMENT INSPECTED			
State Number: 24949	Type of Unit: Passenger Manuf: OTIS Installed: 06/26/2007 Complied:		Floor to Floor: 1 to 2 Speed: 100 Rope Size: Entrances: 1		
Capacity: 2500					
Landings: 2					
Volts: 480					
OWNER	OCCUPANT				
TRINITY UNITED METHODIST CHURCH			TRINITY UNITED METHODIST CHURCH		
209 E. NASH ST			209 E. NASH ST		
SOUTHPORT, NC, 28461			SOUTHPORT, NC, 28461		
		NSPECTION INFORMATION			
Inspection Date 05/25/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
8.6.4.7.1	Clean the elevator p	1.			
	riting on Corrected Violations Forn	n when the following corrections	Elevator Name: # 1 e following corrections have been made in order to bring your equipment into		
complainace with current codes. Violations pointed out to: Wend			Inspector		
_					
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	TRINITY UNITED METHODIST CHURCH An invoice will be mailed to: 209 E. NASH ST SOUTHPORT, NC, 28461				