NCDOL NCDOL N. Department of labor

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10166-48-2462 State Number H1874

	EQU	IPMENT INSPECTED		
State Number: H1874 Type of Unit: Ha		 nd Lift	Floor to Floor: 1 to 2	
Capacity: 750 Manuf: GARAVE Landings: 2 Installed: 04/10/20			Speed: 17	
		800	Rope Size:	
Volts: 120	Complied: 04/10/2	2008	Entrances: 1	
OWNER		OCCUPANT	OCCUPANT	
BEACH MANAGEMENT	EACH MANAGEMENT PENINSULA CLUBHOUSE			
PO BOX 6569 44 PENINSULA				
OCEAN ISLE BEACH, NC, 2846	59	OCEAN ISLE BEACH, NC, 28469		
	INSPE	CTION INFORMATION		
Inspection Date 06/15/2010	Type Inspection Routine	Certificate Status Not Issued	Inspector 48 - Martin	County BRUNSWICK 10
		VIOLATIONS		
complainace with current codes. Violations pointed out to: UNAVA	g on Corrected Violations Form when		Inspector	oring your equipment into
	o make changes to the invoice mailing			
THIS IS NOT AN	n invoice will be mailed to:	BEACH MANAGEMEN PO BOX 6569 OCEAN ISLE BEACH,	VT	