

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10202-8-1890 State Number 7235

	EQUII	PMENT INSPECTED		
State Number: 7235 Capacity: 1500 Landings: 2 Volts: 220	Type of Unit: Passenger Manuf: THYSSEN KRU Installed: 09/19/1972 Complied: 06/20/2000	PP	Floor to Floor: 1 to 2 Speed: 75 Rope Size: Entrances: 1	
OWNER ANSON CO ADMIN BLDG 101 S. GREENE ST WADESBORO, NC, 28170	Compiled: 00/20/2000	OCCUPANT HAMPTON B ALLEN LIBRAR 120 S GREENE ST WADESBORO, NC, 28170		
	INSPEC	TION INFORMATION		
Inspection Date 07/21/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 8 - Burris	County ANSON 4
		VIOLATIONS		
Items must be corrected by: 08/20/2	2010	Elevator Name: PASSENC	GER ELEVATOR	
Notify the Elevator Bureau in writing o complainace with current codes.	n Corrected Violations Form when	the following corrections have been	n made in order to bring your	equipment into
Violations pointed out to: REP- KIT BREWER			Inspector	
To m	ake changes to the invoice mailing	address please call: 919-733-0372		

ANSON CO ADMIN BLDG

101 S. GREENE ST WADESBORO, NC, 28170