

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10229-36-214 State Number H1854

1

	EC	QUIPMENT INSPECTED			
State Number: <b>H1854</b>	Type of Unit: F	Iand Lift	Floor to Floor: 1	to 2	
Capacity: 750	Manuf: ACCES	SS	Speed: 10		
Landings: 1	Installed: 05/17	Installed: 05/17/2007		Rope Size: 0 Entrances: 2	
Volts: 220	Complied: 05/1	Complied: 05/17/2007			
OWNER		OCCUPANT			
CHURCH OF BURLINGTON	Ī	CHURCH OF BURLINGTON			
152 N MAIN STREET		152 N MAIN STREET			
BURLINGTON, NC, 27217		BURLINGTON, NC, 27217			
	INS	PECTION INFORMATION			
Inspection Date 08/17/2010	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
Jotify the Elevator Bureau in w	riting on Corrected Violations Form w	hen the following corrections l	have been made in order to bri	ng your equipment into	
omplainace with current codes. Violations pointed out to: office					
omplainace with current codes. Violations pointed out to: office	To make changes to the invoice mai				