



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
10232-48-0176
State Number
11519

EQUIPMENT INSPECTED

State Number: 11519	Type of Unit: Passenger	Floor to Floor: 1 to 6
Capacity: 4000	Manuf: SOUTHERN	Speed: 100
Landings: 6	Installed: 09/04/1986	Rope Size: 5/8
Volts: 480	Complied: 10/16/1986	Entrances: 1
OWNER	OCCUPANT	
ELIZABETHTOWN LUMBERTON POWER	ELIZABETHTOWN LUMBERTON POWER	
PO BOX 1899	3100 W BROAD ST	
ELIZABETHTOWN, NC, 28337	ELIZABETHTOWN, NC, 28337	

INSPECTION INFORMATION

Inspection Date 08/20/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BLADEN
-------------------------------	----------------------------	---------------------------------	--------------------------	------------------

9

VIOLATIONS

8.6.1.6	General Maintenance Methods and Procedures CLEAN M.R & GEN.
2.2.5.1	Put the pit lights in proper working order.
2.14.1.4.5	Put the in car stop switch in proper working order. BROKEN
5.1.21.1	Put the in car alarm bell in working order.
8.11.2.3	Perform a 5 year full load safety test

Items must be corrected by: 09/19/2010

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: RANDY COATS

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ELIZABETHTOWN LUMBERTON POWER
PO BOX 1899
ELIZABETHTOWN, NC, 28337