



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
10263-24-5046
State Number
966

EQUIPMENT INSPECTED

| | | |
|--------------------------|-------------------------|------------------------|
| State Number: 966 | Type of Unit: Passenger | Floor to Floor: B to 4 |
| Capacity: 2000 | Manuf: OTIS | Speed: 100 |
| Landings: 5 | Installed: 02/20/1948 | Rope Size: 1/2 |
| Volts: 220 | Complied: 09/17/2003 | Entrances: 1 |

OWNER

35 PATTON CONDO ASSOCIATION
P.O.BOX 1021
ASHEVILLE, NC, 28802

OCCUPANT

35 PATTON CONDO ASSOCIATION
35 PATTON AVE
ASHEVILLE, NC, 28801

INSPECTION INFORMATION

| | | | | | |
|-------------------------------|----------------------------|---------------------------------|-------------------------|--------------------|------|
| Inspection Date 09/20/2010 | Type Inspection Routine | Certificate Status Re-issued | Inspector 24 - Moore | County BUNCOMBE | 11 B |
|-------------------------------|----------------------------|---------------------------------|-------------------------|--------------------|------|

VIOLATIONS

8.6.1.6.2 Take steps to lubricate all parts of the elevator machinery and equipment requiring proper lubrication. Gear box low on gear oil. Not picking on gear / overflow can full.

Items must be corrected by: 10/20/2010

Elevator Name: ELEVATOR # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Mailed/ 828-255-7530

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

35 PATTON CONDO ASSOCIATION
P.O.BOX 1021
ASHEVILLE, NC, 28802