



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
10293-7-4421
State Number
H1026

EQUIPMENT INSPECTED

State Number: **H1026**

Capacity: 495

Landings: 2

Volts: 220

Type of Unit: Hand Lift

Manuf: GARAVENTA

Installed: 02/01/2000

Complied: 02/21/2000

Floor to Floor: 1 to 2

Speed: 20

Rope Size:

Entrances: 2

OWNER

ASHE CO SCHOOLS

PO BOX 604

JEFFERSON, NC, 28640

OCCUPANT

ASHE CO MIDDLE SCHOOL

255 NORTHWEST LANE

WARRENSVILLE, NC, 28693

INSPECTION INFORMATION

Inspection Date
10/20/2010

Type Inspection
Routine

Certificate Status
Re-issued

Inspector
7 - Hoffman

County
ASHE

5

VIOLATIONS

NONE

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: KENNY RICHARDSON 336-246-7175

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ASHE CO SCHOOLS
PO BOX 604
JEFFERSON, NC, 28640