

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10294-7-0030 State Number 19032

EQUIPMENT INSPECTED					
State Number: 19032	Type of Unit: Pas	senger	Floor to Floor: 1 to 2		
Capacity: 2500 Manuf: SOUTHERN Landings: 2 Installed: 05/03/2000		Speed: 100 Rope Size:			
				Volts: 208	Complied: 05/03/
OWNER		OCCUPANT			
LIFE STORE BANK		LIFE STORE BANK			
21 EAST ASHE ST.	ST ASHE ST. 21EAST ASHE ST.				
WEST JEFFERSON, NC, 28	694	WEST JEFFERSON, NC, 28694			
	INSP	ECTION INFORMATION			
Inspection Date 10/21/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 7 - Hoffman	County ASHE 5	
		VIOLATIONS			
NONE					
Notify the Elevator Bureau in y	vriting on Corrected Violations Form wh	en the following corrections have b	een made in order to bring vour e	auinment into	
complainace with current codes	S	en une rone wang verreenens nuve e	our made in order to oring your o	quipinoni mie	
Violations pointed out to: ROBIN KING 336-246-4344			Inspector		
	To make changes to the invoice maili	To make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	LIFE STORE BANK 21 EAST ASHE ST. WEST JEFFERSON, NC, 2869			