



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
10306-48-1956
State Number
21706

EQUIPMENT INSPECTED

State Number: 21706	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: OTIS	Speed: 125
Landings: 2	Installed: 08/28/2003	Rope Size: 0
Volts: 208	Complied: 08/28/2003	Entrances: 1
OWNER	OCCUPANT	
SOUTHERN SHORE VILLAS HOA	SOUTHERN SHORE VILLAGE	
122 SE 58TH. ST	122 SE 58TH ST	
OAK ISLAND, NC, 28645	OAK ISLAND, NC, 28645	

INSPECTION INFORMATION

Inspection Date 11/02/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

8.6.4.7.4 Remove the water from the pit floor.

Items must be corrected by: 11/22/2010

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: UNAVAILABLE

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

SOUTHERN SHORE VILLAS HOA
122 SE 58TH. ST
OAK ISLAND, NC, 28645