NCDOL NCDOL NA Department of John

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10333-12-3927 State Number 5219

EQUIPMENT INSPECTED						
State Number: 5219		Type of Unit: Passenger		Floor to Floor: 1	Floor to Floor: 1 to 2	
Capacity: 2500		Manuf: WESTBROOK		Speed: 75		
Landings: 2		Installed: 07/19/1965		Rope Size:		
Volts: 240		Complied: 05/20/2003		Entrances: 1		
OWNER		OCCUPANT				
DAVID & JANET RICH		COLLECTORS ANTIQUE MALL		LL		
211 SUNSET AVE						
ASHEBORO, NC, 27203		ASHEBORO, NC, 27203				
		IN	NSPECTION INFORMATION			
Inspection Date 11/29/2010		Type Inspection Routine	Certificate Status Re-issued	Inspector 12 - Essick	County RANDOLPH	
			VIOLATIONS			
8.11	l Perform annual test					
8.6.1	Provide a written maintenance control program					
3.7 Repair equipment room door lock						

Items must be corrected by: 12/29/2010

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: Jack Gorham, Mgr, 336 629 8105 Inspector

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

An invoice will be mailed to:

DAVID & JANET RICH 211 SUNSET AVE ASHEBORO, NC, 27203