

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10333-36-2389 State Number H79

1

| | EQU | JIPMENT INSPECTED | | |
|---|--------------------------------------|--|--------------------------------|------------------------|
| State Number: H79 | Type of Unit: Hand L | ift | Floor to Floor: 1 to | 2 |
| Capacity: 500 | Manuf: TOCE | | Speed: 12 | |
| Landings: 2 | Installed: 01/07/1982 | | Rope Size: | |
| Volts: 110 | Complied: 01/07/1982 | 2 | Entrances: 2 | |
| OWNER | OCCUPANT | | | |
| FIRST BAPTIST CHURCH | FIRST BAPTIST CHURCH | | | |
| PO BOX 2686 | 400 S BROAD ST | | | |
| BURLINGTON, NC, 27216-2686 | i | BURLINGTON, NC, 27215 | | |
| | INSPE | CTION INFORMATION | | |
| Inspection Date 11/29/2010 | Type Inspection Routine | Certificate Status Re-issued | Inspector 36 - Kirkman | County ALAMANCE |
| | | VIOLATIONS | | |
| none found at time of inspection | | | | |
| none round at time of inspection | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| otify the Elevator Bureau in writir mplainace with current codes. | ng on Corrected Violations Form whe | n the following corrections l | have been made in order to bri | ng your equipment into |
| iolations pointed out to: mrs. Cof | | | | |
| | o make changes to the invoice mailin | | | |
| THIS IS NOT AN | n invoice will be mailed to: | FIRST BAPTIST CHUR PO BOX 2686 BURLINGTON NC 277 | СН | |