



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
10333-48-3415
State Number
H1132

EQUIPMENT INSPECTED

State Number: H1132	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: SAVARIA	Speed: 14
Landings: 2	Installed: 05/17/2001	Rope Size:
Volts: 120	Complied: 05/17/2001	Entrances: 2
OWNER	OCCUPANT	
DANNY LEONORD - DOT KENNEDY	INTRACOASTAL REALTY CORP.	
PO BOX 775	128 COUNTRY CLUB DR	
OAK ISLAND, NC, 28465	OAK ISLAND, NC, 28465	

INSPECTION INFORMATION

Inspection Date 11/29/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

n/a No violations found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: EVELYN JOHNSON

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

DANNY LEONORD - DOT KENNEDY
PO BOX 775
OAK ISLAND, NC, 28465