



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**10333-48-3795**  
State Number  
**11693**

EQUIPMENT INSPECTED

State Number: <b>11693</b>	Type of Unit: Passenger	Floor to Floor: G to 3
Capacity: 2000	Manuf: KONE	Speed: 125
Landings: 4	Installed: 02/19/1987	Rope Size: .
Volts: 0	Complied: 02/19/1987	Entrances: 4

OWNER

WEST BEACH VILLA  
2714 W BEACH DRIVE  
LONG BEACH, NC, 28461

OCCUPANT

WEST BEACH VILLA  
2714 W. BEACH DRIVE  
LONG BEACH, NC, 28461

INSPECTION INFORMATION

Inspection Date 11/29/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

8.6.4.9	Clean the elevator car top. NUMEROUS RUST SPOTS
8.6.4.7.4	Remove the water from the pit floor.

Items must be corrected by: 12/29/2010

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: UNAVAILABLE

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

WEST BEACH VILLA  
2714 W BEACH DRIVE  
LONG BEACH, NC, 28461