



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
10350-16-5983
State Number
6120

EQUIPMENT INSPECTED

State Number: 6120	Type of Unit: Passenger	Floor to Floor: 1 to 4
Capacity: 4000	Manuf: OTIS	Speed: 200
Landings: 4	Installed: 07/28/1968	Rope Size: 5/8
Volts: 208	Complied: 01/07/1969	Entrances: 1

OWNER
BEAUFORT COUNTY HOSPITAL
628 E 12TH ST
WASHINGTON, NC, 27889

OCCUPANT
BEAUFORT COUNTY HOSPITAL
628 E 12TH ST
WASHINGTON, NC, 27889

INSPECTION INFORMATION

Inspection Date 12/16/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 16 - Moore	County BEAUFORT
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

7

VIOLATIONS

8.6.4.9	Clean the elevator car top.
8.6.4.15	Take steps to place the car emergency telephone in proper working order.

Items must be corrected by: 01/15/2011

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Stan Maintenance Chief

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BEAUFORT COUNTY HOSPITAL
628 E 12TH ST
WASHINGTON, NC, 27889