

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 10357-36-1229 State Number 11748

1

	E	QUIPMENT INSPECTED			
State Number: 11748	Type of Unit: Passenger		Floor to Floor:	Floor to Floor: 1 to 2	
Capacity: 4000	Manuf: THYSSEN KRUPP		Speed: 125		
Landings: 2	Installed: 08/04/1987		Rope Size:		
Volts: 208	Complied: 08/04/1987		Entrances: 1		
OWNER	OCCUPANT				
ELON UNIVERSITY	ELON UNIV / MODEL FINE ARTS				
803 HAGGARD AVENUE	207 N WILLIAMSON AVE				
ELON, NC, 27244		ELON, NC, 27244			
	INS	PECTION INFORMATION			
Inspection Date 12/23/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
NONE FOUND					
NONETOCKE					
	iting on Corrected Violations Form w	when the following corrections l	nave been made in order to bri	ng your equipment into	
complainace with current codes. Violations pointed out to: Bob W	7:11;c 23.6 278 2000		Inchestor		
•	······································				
THE ISSUE AND	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	ELON UNIVERSITY 803 HAGGARD AVENU ELON, NC, 27244	JE		