



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
11010-36-2746
State Number
12179

EQUIPMENT INSPECTED

State Number: 12179	Type of Unit: Dumbwaiter	Floor to Floor: B to 3
Capacity: 200	Manuf: ATLAS	Speed: 50
Landings: 4	Installed: 12/30/1986	Rope Size: 1/4
Volts: 240	Complied: 12/30/1986	Entrances: 1

OWNER

BURLINGTON INSURANCE GROUP
238 INTERNATIONAL
BURLINGTON, NC, 27215

OCCUPANT

BURLINGTON INSURANCE GROUP
238 INTERNATIONAL
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 01/10/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

none found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: jack336-229-9090

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BURLINGTON INSURANCE GROUP
238 INTERNATIONAL
BURLINGTON, NC, 27215