

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 11010-36-5094 State Number 19552

1

	E	QUIPMENT INSPECTED			
State Number: 19552	Type of Unit: Passenger		Floor to Floor:	Floor to Floor: L to 2	
Capacity: 2100	Manuf: THYSSEN	Manuf: THYSSEN KRUPP			
Landings: 3	Installed: 09/15/2000		Rope Size:	Rope Size:	
Volts: 200	Complied: 11/07/2000		Entrances: 1		
OWNER		OCCUPANT			
TRINITY WORSHIP CENTER		TRINITY WORSHIP CENTER			
3157 S CHURCH ST		3157 S CHURCH ST			
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
	INS	SPECTION INFORMATION			
Inspection Date 01/10/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
none found					
Notify the Elevator Bureau in writi omplainace with current codes.	ing on Corrected Violations Form v	when the following corrections l	have been made in order to bri	ng your equipment into	
Violations pointed out to: mary 336-585-0605			Inspector		
	Γo make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	TRINITY WORSHIP CE 3157 S CHURCH ST BURLINGTON NC 27			