



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**11013-36-5745**  
State Number  
**24721**

#### EQUIPMENT INSPECTED

State Number: <b>24721</b>	Type of Unit: Passenger	Floor to Floor: 1 to 4
Capacity: 5000	Manuf: TKE	Speed: 350
Landings: 4	Installed: 06/25/2008	Rope Size: 3/4
Volts: 480	Complied:	Entrances: 1
OWNER	OCCUPANT	
LABCORP	LABCORP HEADQUARTERS	
531 S SPRING STREET	531 S SPRING STREET	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

#### INSPECTION INFORMATION

Inspection Date 01/13/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

#### VIOLATIONS

8.6.5.10 The minimum car and counterweight clearances and runby shall be maintained in compliance with the applicable code when replacement suspension ropes are installed or when existing suspension ropes are shortened.

Items must be corrected by: 02/12/2011

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: LORIE FLINCHUM336-436-7777

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

LABCORP  
531 S SPRING STREET  
BURLINGTON, NC, 27215