N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
11018-49-0567
State Number
4865

EQUIPMENT INSPECTED

State Number: **4865**	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 10000	Manuf: OTIS	Speed: 60
Landings: 2	Installed: 04/16/1963	Rope Size:
Volts: 560	Complied: 04/19/1990	Entrances: 2

OWNER
AVOCA INC
PO BOX 129
MERRY HILL, NC, 27957

OCCUPANT
AVOCA INC.
841 AVOCA FARM ROAD
MERRY HILL, NC, 27957

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County
01/18/2011	Routine	Re-issued	49 - Hayes	BERTIE

8

VIOLATIONS

n/a No violations found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: Warren Jones 252-482-0404 Inspector _____

THIS IS NOT AN INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:
AVOCA INC
PO BOX 129
MERRY HILL, NC, 27957