



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
11025-16-1937
State Number
10891

EQUIPMENT INSPECTED

State Number: 10891	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: OTIS	Speed: 75
Landings: 2	Installed: 02/16/1984	Rope Size: 0
Volts: 480	Complied: 11/03/2003	Entrances: 1
OWNER	OCCUPANT	
BEAUFORT COUNTY	BEAUFORT CO COMMUNITY COLLEGE	
PO BOX 1069	5337 HWY 264 EAST	
WASHINGTON, NC, 27889	WASHINGTON, NC, 27889	

INSPECTION INFORMATION

Inspection Date 01/25/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 16 - Moore	County BEAUFORT
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

7

VIOLATIONS

n/a No violations found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Melvin Lodge

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BEAUFORT COUNTY
PO BOX 1069
WASHINGTON, NC, 27889