



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
11046-36-3737
State Number
25205

EQUIPMENT INSPECTED

State Number: 25205	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 3500	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 09/25/2007	Rope Size:
Volts: 208	Complied: 09/25/2007	Entrances: 1
OWNER	OCCUPANT	
JULIE BLUE WILLIAMS	FIVE STAR BUILDING	
P O BOX 1447	104 E CENTER STREET	
HILLSBOROUGH, NC, 27278	MEBANE, NC, 27302	

INSPECTION INFORMATION

Inspection Date 02/15/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

NONE FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: ANN BAIZE 336-563-0773

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

JULIE BLUE WILLIAMS
P O BOX 1447
HILLSBOROUGH, NC, 27278