



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
11046-36-5996
State Number
23204

EQUIPMENT INSPECTED

State Number: 23204	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 10/18/2005	Rope Size:
Volts: 480	Complied: 10/18/2005	Entrances: 1

OWNER

CITY OF MEBANE
106 EAST WASHINGTON ST
MEBANE, NC, 27302

OCCUPANT

MEBANE PUBLIC LIBRARY
2ND & WASHINGTON ST
MEBANE, NC, 27302

INSPECTION INFORMATION

Inspection Date 02/15/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

none found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Sherry (919) 563-6431

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CITY OF MEBANE
106 EAST WASHINGTON ST
MEBANE, NC, 27302