



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**11047-36-4097**  
State Number  
**H225**

EQUIPMENT INSPECTED

State Number: <b>H225</b>	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 500	Manuf: PORCHLIFT	Speed: 10
Landings: 2	Installed: 06/16/1987	Rope Size:
Volts: 110	Complied: 06/16/1987	Entrances: 2
OWNER	OCCUPANT	
NORTHSIDE CHURCH OF CHRIST	NORTHSIDE CHURCH OF CHRIST	
PASTOR ROBERT BREWINGTON	820 HARRIS STREET	
BURLINGTON, NC, 27216	BURLINGTON, NC, 27216	

INSPECTION INFORMATION

Inspection Date 02/16/2011	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------------	----------------------------------	---------------------------	--------------------

1

VIOLATIONS

This Bdlg still has a elevator notification on the door. I will try again later!

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complianace with current codes.

Violations pointed out to: n/a

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

NORTHSIDE CHURCH OF CHRIST  
PASTOR ROBERT BREWINGTON  
BURLINGTON, NC, 27216