



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
11052-36-3591
State Number
9974

EQUIPMENT INSPECTED

State Number: 9974	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 4000	Manuf: THYSSEN KRUPP	Speed: 125
Landings: 2	Installed: 11/10/1981	Rope Size:
Volts: 480	Complied: 11/10/1981	Entrances: 1

OWNER
MEDTOX DIAGNOSTICS, INC
1238 ANTHONY RD
BURLINGTON, NC, 27215

OCCUPANT
MEDTOX DIAGNOSTICS, INC
1238 ANTHONY RD
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 02/21/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

NONE FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: MARK 336-226-6311

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

MEDTOX DIAGNOSTICS, INC
1238 ANTHONY RD
BURLINGTON, NC, 27215