NCDOL NCDOL NA Department of John

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 11083-48-5283 State Number 22801

		EQUIPMENT INSPECTED			
State Number: 22801 Type of U		ssenger	Floor to Floo	Floor to Floor: G to 3	
Capacity: 3000	Manuf: THYSSE		Speed: 125		
Landings: 4	Installed: 01/26/2005		Rope Size: Entrances: 1		
Volts: 208 Complied:		/2007			
OWNER	•	OCCUPANT			
CAM	ISLANDER RESORT - BLDG. #61 122 VIA OLD SOUND BLVD				
P.O. BOX 8126					
OCEAN ISLE BEACH, NC, 284	169	OCEAN ISLE BEACH, NC, 28469			
		NSPECTION INFORMATION			
Inspection Date 03/24/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
Items must be corrected by: 04	4/03/2011				
otify the Elevator Bureau in writ mplainace with current codes.	ing on Corrected Violations Form	when the following corrections	have been made in order to	bring your equipment into	
iolations pointed out to: UNAV			Inspector		
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	CAM P.O. BOX 8126 OCEAN ISLE BEACH.	NC. 28469		